WA-I-518 Frame House
Mid-20th century
Hagerstown Vicinity

Private

The Frame House is a one and one-half story, three-bay by two-bay structure on a concrete foundation. It has a gable front main facade with a gable roof covered in asphalt shingle. The main facade also has a hipped porch roof, a small concrete entrance porch and a side entrance plan. The house has a rectangular plan and appears to have been constructed in the mid-20th century.

## Maryland Historical Trust State Historic Sites Inventory Form

Magi No.
DOE \_\_yes \_\_no

1. Nam	1e (indicate pr	eferred name)			
historic Fr	ame house				
and/or common	×		El		
2. Loca	ation			41.6	
street & number	east side of Rt.	65, .27 mile south o	f I-70 _	not for publication	
city, town Hage		_x_ vicinity of	congressional district	sixth	
Mon	yland			BIAGI	
State	sification	county	Washington	W is	
Category district building(s) structure site object	Ownership public private both Public Acquisition in process being considerednot_applicable	Status occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:	
name street & number	er of Prope	(give names an	d mailing addresses		
city, town state			and zip code		
5. Loca	ation of Leg	al Description	n		
courthouse, regi	istry of deeds, etc. Was	nington County Court	nouse	liber	
street & number	Washington Street	et		folio	
ony, town	gerstown		state	Maryland	
6. Rep	resentation	in Existing	Historical Surv	eys	
title					
date			federal stat	e county loca	
depository for si	urvey records				
city, town			state		

Condition excellent	deteriorated	Check one unaltered	Check one original site
good fair	ruins unexposed	altered	moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a one and one-half story, three-bay by two-bay structure on a concrete foundation. It has a gable front main facade with a gable roof covered in asphalt shingle. The main facade also has a hipped porch roof, a small concrete entrance porch and a side entrance plan. The house has a rectangular plan and appears to have been constructed in the mid-20th century.

The frame house is located on the east side of Rt. 65, .27 mile south of I-70. It is situated in a cluster of buildings from the mid-20th century to the present time.

The walls of the structure are covered in white siding. The roof has two shed-roof dormer windows on both sides of the gable roof. The main facade has a entrance on one side and a two-section window on the other. There is a two-section window in the gable. A brick flue is located at the peak of the roof about three-quarters of the way towards the rear of the building. In the rear of the building is a small addition with a shed roof.

There are significant outbuildings on this property.

8.	Sign	ificance	
----	------	----------	--

Survey No. WA-I-498 5/8

Period preh	D-1499 archeology-historic D-1599 agriculture D-1699 architecture D-1799 art D-1899 commerce	check and justify below	literature military music t philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates	Builder/Architect		
check:	Applicable Criteria:A and/or Applicable Exception:		EFG	
	Level of Significance:			
Prepare	both a summary paragraph	of significance and	a general statement of	history and

Based on the MHT Survey Matrix, this is a minimal site due to its recent date of construction.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

state

Maryland

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Annapolis

city or town

Maryland Historical Trust


Shaw House

21 State Circle


Annapolis, Maryland 21401

(301) 269-2438

WA-I-518 Frame House 10427 Sharpsburg Pike (MD 65) Funkstown Quadrangle



1993-94 Aerial Photo





- l. Frame House WA-I-498-5/8
- 2. Washington County, Maryland
- 3. Joe Getty
- 4. May 1983
- 5. Maryland Hist. Trust, Annapolis, Md.
- 6. West Elevation; camera facing east
- 7. 1/1